Scope of Work for Property Located at:					2028 W Wright St			
	Property is: Sin	gle Family		Dup	lex		\mathbf{x}	Commerical
Date:	4/13/2010							
take no respor		covered after t	he ins	pectio	n dat	e, or for omission	ons through error	development Authority, and their representatives or oversight. The list does not necessarily include tms.
Exterior C	ondition Report	t						
Location Site	Required Work Landscaping	n/a		Yes		Note/Comm Self Help	ents	Cost \$
	Steps/Handrails	n/a		Yes				\$
	Service walks	n/a		Yes				\$
	Fencing	n/a		Yes				\$
	Parking	n/a	П	Yes				\$
	Retaining walls	n/a		Yes				\$
	Other	n/a		Yes				\$
	Other	n/a		Yes				\$
Garage	Singles: repair	n/a	П	Yes				\$
	Shingles: Roof over ex	disting n/a		Yes				\$
	Shingles:Tear off & re-	roof n/a		Yes				\$
	Gutters/downspouts	n/a		Yes				\$
	Flashing	n/a		Yes				\$
	Eaves	n/a		Yes				\$
	Siding	n/a		Yes				\$
	Doors	n/a		Yes				\$
	Windows	n/a		Yes				\$
	Slab	n/a		Yes				\$
	Paint	n/a		Yes				\$
	Electrical	n/a		Yes				\$
	Other	n/a		Yes				\$
	Roof	n/a	П	Yes [\$
	Deck-upper	n/a		Yes		**************************************		\$
	Decklower	n/a	П	Yes				\$
	Steps/handrails	n/a		Yes [\$
	Ceiling	n/a		Yes [\$
	Guardrails	n/a		Yes [\$
	Structural	n/a		Yes [\$
	Paint	n/a		Yes [\$
,	Other	n/a		Yes [\$

House

Chimney	n/a Yes X	\$ 1,500.00
Shingles: repair	n/a Yes	\$
Shingles: roof over existing	n/a Yes	\$
Shingles:Tear off & re-roof	n/a Yes	\$
Gutters/downspouts	n/a Yes	\$
Flashing	n/a Yes	\$
Eaves	n/a Yes	\$
Siding	n/a Yes	\$
Storm Doors	n/a Yes	\$
Prime ("main") Doors	n/a Yes	\$
Storm Windows	n/a Yes	\$
Prime ("main") Windows	n/a Yes	\$
Paint	n/a Yes	\$
Foundation	n/a Yes	\$
Electrical	n/a Yes	\$
Other	n/a Yes X Flat roof with deck	\$ 32,000.00
Other	n/a Yes X Parapet wall	\$ 12,000.00
Other	n/a Yes	\$
Other	n/a Yes	\$

Exterior: Estimated Cost:*

\$

45,500.00

^{*}average contracted cost. Actual costs may vary. Self help will reduce the amount.

Interior Co	ondition Report				punnany		
	Unit: Entire unit (single family)) 📙		Lower unit of duplex	×	Commerical	
Mechanical Heating	Upper unit of duplex Required Work			Other		Commenca	
	Repair/replace boiler	n/a	Yes		where the same and	\$	********************************
	Repair radiation	n/a	Yes 🗌			\$	***************************************
	Repair/replace furnace	n/a	Yes X			\$	12,000.00
	Repair ductwork	n/a	Yes X			\$	4,500.00
	Replace thermostat	n/a	Yes 🗌			\$	600.00
	Repair/replace grilles	n/a	Yes			\$	1,200.00
mr	Tune boiler/furn. insp ht exchan	g n/a	Yes 🗌			\$	atualismus est extension except of the property of
Electrical	Repair/replace receptacles	n/a	Yes X			\$	1,500.00
	Repair/replace switches	n/a	Yes X			\$	1,500.00
	Repair/replace fixtures	n/a	Yes X			\$	1,500.00
	Install outlets and circuits	n/a	Yes 🗌			\$	
	Install outlets and circuits	n/a	Yes			\$	
	Install outlets and circuits	n/a	Yes 🗌			\$	
	Install outlets and circuits	n/a	Yes 🗌			\$	
	Upgrade service	n/a	Yes X			\$	4,200.00
	Other	n/a	Yes 🗌			\$	
	Other	n/a	Yes 🗌	enter a la companya de la companya		\$	
Plumbing	Repair/replace kitchen sink	n/a	Yes 🗌	<u></u>		\$	2,000.00
	Repair/replace kitchen sink fauc	€ n/a	Yes			\$	600.00
	Repair/replace tub	n/a	Yes 🗌			\$	6,000.00
	Repair/replace tub faucet	n/a	Yes 🗌			\$	600.00
	Repair/replace toilet	n/a	Yes X			\$	2,400.00
	Repair/replace lavatory	n/a	Yes X			\$	2,200.00
	Repair/replace lavatory faucet	n/a	Yes X			\$	600.00
	Repair/replace wash tub	n/a	Yes 🗌			\$	
	Repair/replace wash tub faucet	n/a	Yes			\$	
	Unclog piping:	n/a	Yes			\$	
	Repair drain/waste/vent piping	n/a	Yes X	·		\$	1,500.00
	Repair water piping	n/a	Yes X			\$	2,500.00
	Repair/replace water heater	n/a	Yes X			\$	6,000.00
	Other	n/a	Yes 🗌			\$	

n/a

Other

Yes

				Total Exterior and Interior Cost:*	\$ 130,025.00
				Interior: Estimated Cost:	\$ 84,525.00
		n/a	Yes		\$
		n/a	Yes]	\$ ***************************************
	Marie Control of the	n/a	Yes		\$
		n/a	Yes X	Asbestos removal	\$ 2,500.00
Other	Repair defective	n/a	Yes		\$
Floors		, ,		1	
Stairs	Repair defective	n/a	Yes		\$
	Repair/replace defective	n/a	Yes	Self Help	\$
Handrails	Install smoke alarm: 2nd flr.	n/a	Yes	Self Help	\$
	Install smoke alarm: 1st flr.	n/a	Yes	Self Help	\$
	Install smoke alarm:bsmt.	n/a	Yes	Self Help	\$
Fire Safety				7	
	Repair or repl. @ defective	n/a	Yes X	1	\$ 6,500.00
Paint					
Walls/Ceilin	gs Repair or repl. @ defective	n/a	Yes X	7	\$ 12,500.00
14. 11. 10. 11.	Repair or repl. locks/latches	n/a	Yes	Self Help	\$
Doors	Repair or replace doors	n/a	Yes		\$
Doors	Repair or replace sash	n/a	Yes		\$ 11,625.00
	Replace broken glass	n/a	Yes		\$
Windows					

Prepared by Dennis Nutting

4/13/2010

Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

Important Information Regarding Permits

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located on the first floor of 841 N. Broadway. If you will be occupying the home, you can get free lead-safe training from the Health Department! Call 286-5119 to schedule on-site training.

^{*}average contracted cost. Actual costs may vary. Self help will reduce the amount.